

VEHICLE INSPECTION REPORT

PF70CBV

Mercedes-Benz Sprinter 315 CDI PROGRESSIVE

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 26/02/2021

Year 2021

Mileage 121,408 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN W1V9076332P313781

Body Style Panel Van L2

MOT Due 19/01/2027

CAP Clean £10,450.00

CAP Average £9,350.00

CAP Below £7,675.00

Gearbox MANUAL

Gears 6

RACKING IN REAR

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Qtr Panel nsr
Dented
Over 30mm

4: Sill ns
Dented
With Paint Damage



5: Qtr Panel nsr
Dented
Over 30mm

6: Qtr Panel nsr
Dented
Over 30mm



7: Door nsr
Scratched
Over 25mm Thru Paint

8: Door osr
Dented
With Paint Damage



9: Qtr Panel osr
Dented
Over 30mm

10: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



11: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

12: Qtr Panel osr
Dented
With Paint Damage



13: Qtr Panel osr
Dented
Over 30mm

14: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



15: Seat Base Cover osf
Soiled
Heavy

16: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		No
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			